





WS401CCV & WS402CCV









WS401CVX & WS402CVX







INSTRUCTIONS FOR WS401:

- 1. PLACE BUMPER ON WALL AND LOCTE THE MOUNTING HOLE.
- 2. DRILL A $\frac{1}{4}$ " (6) DIAMETER HOLE.
- 3. INSERT PLASTIC ANCHOR IN HOLE.
- 4. USING A #2 PHILLIPS SCREWDRIVER, MOISTEN TIP OF SCREWDRIVER.
- 5. FORCE SCREWDRIVER THRU SMALL HOLE IN CENTER OF RUBBER TO GET TO HEAD OF SCREWDRIVER.
- ALLOW BUMPER TO ROTATE AS SCREW IS TIGHTENED.

INSTRUCTIONS FOR WS402:

- I. PLACE BUMPER ON WALL AND LOCTE THE MOUNTING HOLE.
- 2. DRILL A $\frac{5}{16}$ " (8) DIAMETER HOLE.
- 3. INSERT DRY WALL ANCHOR IN HOLE. 4. USING A #2 PHILLIPS SCREWDRIVER,
- MOISTEN TIP OF SCREWDRIVER.
- 5. FORCE SCREWDRIVER THRU SMALL HOLE IN CENTER OF RUBBER TO GET TO HEAD OF SCREWDRIVER.
- ALLOW BUMPER TO ROTATE AS SCREW IS TIGHTENED.

	QTY	SCREW DETAILS
WS401	1	#10 X I" FPHSMS
	1	#10 PLASTIC ANCHOR
WS402	1	#8 X 11/4" OPHWS
	1	DRY WALL ANCHOR





