




- Notes:**
- 1. Do not scale drawing.
 - 2. Right Hand Shown.
 - 3. All dimensions given in inches. Conversion from inches to metric: inch x 25.4
 - 4. Solid door line represents door in open position with closer wound. Dashed door line represents door in closed position with closer at rest.
 - 5. See IP50500 A & B for door mortising.
 - 6. Consult factory for door thickness other than 1-3/4" or for extended spindle lengths.