



WS447





INSTRUCTIONS:

- PLACE HOLDER ON WALL AND LOCATE MOUNTING HOLES.
- 2. PREPARE MOUNTING HOLES.
- 3. INSTALL HOLDER.

| | QTY | SCREW DETAILS |
|-------|-----|--------------------------|
| WS443 | 1 | 3/8-12 THREADED STUD |
| | 1 | LEAD SHIELD |
| | 1 | #8 X I" OPHWS |
| | 1 | LEAD SHIELD |
| WS447 | 3 | #12 X 1-1/4" OPHSMS |
| | 3 | PLASTIC EXPANSION SHIELD |







