


INSTALLATION INSTRUCTIONS FOR TRUNNION MOUNT BRACKET

Item #: F-ARL-TR MOUNT

Used on products: F-ARL-300W/50K/P3 and F-ARL-300W/50K/P5




1

Note: Pole mount, back plate, shorting cap and existing hardware are not needed.




2

Secure metal spacers (b) to both sides of area light with screws (d) using a 3mm hex key.



3

Place (1) locking washer, (1) washer, and (1) star washer on bolt in this order:



4

Secure mounting bracket, bolts and washers to area light using a 8mm hex key. Do not tighten fully. Adjust mounting bracket to desired position, then tighten down to lock mounting angle.

