






# FM83SLISF

## TEMPLATE FULL MORTISE CONTINUOUS GEARED ALUMINUM HINGE




**\*\* CAUTION \*\***  
Due To Frame  
Installation  
Variations,  
Pre-drilling  
For Fasteners  
Is Not  
Recommended

Opening Clearances at 90°



Opening Clearances at 180°







Concealed Circuit (CC) Application  
Not Available

Magnetic Monitor (MM) Application  
Not Available


# FM85SLISF

## TEMPLATE FULL MORTISE CONTINUOUS GEARED ALUMINUM HINGE




**\*\* CAUTION \*\***  
Due To Frame  
Installation  
Variations,  
Pre-drilling  
For Fasteners  
Is Not  
Recommended

Opening Clearances at 90°



Opening Clearances at 180°






Concealed Circuit (CC) Application  
Not Available


Magnetic Monitor (MM) Application  
Not Available

# FM95SLISF

# TEMPLATE FULL MORTISE CONTINUOUS GEARED ALUMINUM HINGE




DO NOT SCALE




\* \* CAUTION \* \*

Due To Frame  
Installation  
Variations,  
Pre-drilling  
For Fasteners  
Is Not  
Recommended

Opening Clearances at 90°



Opening Clearances at 180°






Concealed Circuit (CC) Application  
Not Available

Magnetic Monitor (MM) Application  
Not Available


# FM120SLISF

## TEMPLATE FULL MORTISE CONTINUOUS GEARED ALUMINUM HINGE




DO NOT SCALE


**\*\* CAUTION \*\***  
Due To Frame  
Installation  
Variations,  
Pre-drilling  
For Fasteners  
Is Not  
Recommended



Opening Clearances at 90°



Opening Clearances at 180°



Concealed Circuit (CC) Application  
Not Available

Magnetic Monitor (MM) Application  
Not Available