

INSTALLATION GUIDE

Read Before Installation:



Read before installation! Failure to do so may result in improper adhesion.

Storage and shelf life: All adhesive gaskets have a limited shelf life. This product must be used within 6 months of purchase and must be stored between 50°F and 100°F.

<u>Before installing</u>: The surface should be clean, dry and free of dust, grease, oil or solvents. Avoid quick dry primers which often leave a powdered, improperly adhered paint surface; this type of surface responds like dust, preventing good adhesion to self-sticking backings.


<u>Application temperature</u>: FG3000 will have the optimum adhesion when installed in a clean dry frame between $65^{\circ}F(18^{\circ}C)$ and $80^{\circ}F(26^{\circ}C)$. For proper performance, do not install on a frame at less than $50^{\circ}F(10^{\circ}C)$ or more than $100^{\circ}F(37^{\circ}C)$.

Installation Instructions:

FG3000S45 in 20-min. and 45-min. Sidelite / Borrowed Lite / Transom Lite on Hollow Metal Frame (Screen)



FG3000S45 in 20-min. Wood Sidelite / Borrowed Lite/ Transom Lite with Wood Frame and All Wood Construction




FG3000S45 in 20-min. and 45-min. Hollow Metal Doors

FG3000S45 applied to both sides of the frame

LT-B1

FG3000S45

FG3000S45 in 20-min. and 45-min. Wood Doors



Phone: 845-388-1300

Fax: 845-367-4657

Door and frame must be manufactured by companies which are classified by Underwriters Laboratories Inc.® for the manufacturing and labeling of fire doors and frames. Warnock-Hersey (I.T.S.) listings are also available through participating manufacturers.