




**TRADEMARK
HARDWARE**

WORLD OF QUALITY HARDWARE



NOTE: If "S" dimension is other than $\frac{5}{8}$ " advise the factory.

Order Size= L (complete width opening) - S (Door Stop width)

or

Order Size= F (Filler Size) + E (Coordinator Size)

